

Table of Contents

Fiat->Fiat OEM Rubber Gaskets->508 C Nuova Balilla	
Terms and Conditions	





Fiat OEM Rubber Gaskets->508 C Nuova Balilla



508 C Nuova Balilla Rubber...

12097-000

Rubber carpet set for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...



508 C Nuova Balilla Rubber...

12097-001

\$225

Rubber carpet no. 1 for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...



508 C Nuova Balilla Rubber...

12097-002

Rubber carpet no. 2 for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...

\$225



508 C Nuova Balilla Rubber...

12097-003

\$486

Rubber carpet no. 3type cloche gearfor Fiat 508 C Nuova Balilla models from 1937-39. There...



508 C Nuova Balilla Cowling...

12097-004

Cowling articulation gear lever no. 4 for Fiat 508 C Nuova Balilla models from 1937-39...



508 C Nuova Balilla Windshield...

12097-100

Windshield gasket for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...

\$378



508 C Nuova Balilla Rear...

12097-110

\$238

\$216

Rear windshield gasket for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3...



508 C Nuova Balilla Door On...

12097-163

\$40

Door on body lower gasket set or Fiat 508 C Nuova Balilla models from 1937-39. There is





508 C Nuova Balilla Door On...

12097-172

Door on body higher gasket set for Fiat 508 C Nuova Balilla models from 1937-39. There is...

\$99



508 C Nuova Balilla Centre...

12097-175

Centre door gasket set for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3...



508 C Nuova Balilla Rubber...

12097-180

Rubber under head bonnet for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3...



508 C Nuova Balilla Fixed...

12097-220

Fixed bumper rubber for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...

508 C Nuova Balilla

\$104



508 C Nuova Balilla Rubber...

12097-240

\$104

Rubber ring tank for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...



508 C Nuova Balilla Headlamp...

12097-280

\$26

Headlamp gasket set for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...



Pedal... 12097-291

Pedal cover accelerator for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3...

508 C Nuova Balilla

\$28



508 C Nuova Balilla Gear Lever...

12097-305


Gear lever cowling for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...



508 C Nuova Balilla Dust...

12097-307

Dust protection under pedal clutch and brake for Fiat 508 C Nuova Balilla models from...



External... 12097-310

External window scrapper set for Fiat 508 C Nuova Balilla models from 1937-39. There is

\$82



508 C Nuova Balilla Bushing...

12097-710

\$78

Bushing suspension rubber for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3...



508 C Nuova Balilla Window...

12097-830

\$41

Window channel set for Fiat 508 C Nuova Balilla models from 1937-39. There is a 2-3 week...





508 C Nuova Balilla Fuel Tank

FG-T500-052

Fuel tank for Fiat 508 C Nuova Balilla models. Part #: EG-T500-052

\$525





Fiat OEM Rubber Gaskets->508 C Nuova Balilla



508 C Nuova Balilla Wheel...

RS-T500-006

This is ONE wheel brass bolt for Fiat 508 C Nuova Balilla models. Diameter: 22 x 33.5 mm...

\$10



508 C Nuova Balilla Wheel Bolt

RS-T500-007

This is ONE wheel bolt for Fiat 508 C Nuova Balilla models. Part #: RS-T500-007

\$8

Page 3



TERMS AND CONDITIONS

PRICES:

We make a real effort to keep our prices as low as possible; however, all prices are subject to change without notice. Most of our parts are imported directly from European manufacturers to give you the best possible prices.

STANDARD RETURN POLICY:

- You have 14 calendar days to return an item from the date you received it.
- Please ensure that the item(s) you're returning is repackaged as received

Italian Auto Parts, Inc 2370 John Glenn Dr Atlanta, Ga 30341 United States

Phone: 1-877-9MRFIAT (1-877-967-3428)

Fax: 914-829-9018

SHIPPING CLAIMS:

We receive excellent service from Fedex and the USPS, although occasionally a mishap occurs. Open any damaged packages in the presence of the carrier, and call us immediately so we can file a claim. If a package arrived damaged all packaging materials must be kept and may be collected and inspected by the carrier when investigating a claim. Missing packages must be reported to Italian Auto Parts, Inc in a timely manner to enable us to file a claim with the carrier. On any orders shipped by truck freight, signing for a shipment constitutes an acknowledgement that the order has been received in good condition; Italian Auto Parts, Inc cannot be held responsible for damage once a truck freight package has been signed for.

